

SPARTAN CHASSIS INTERNAL DOCUMENT - FOR INTERNAL USE

**SERVICE INFORMATION RECOMMENDED FOR VANTIVE
Fire Trucks with Tandem Drive Dynalastic Suspension
June 30, 2003**

The end-users for each of the Sales Order Numbers listed below may or may not have registered a complaint with Customer Service about the vehicle “not sitting level”, “motor boating”, or “sitting too low in the back”.

Please check the service information recorded in Vantive for each vehicle listed:

If there is not a service repair on record addressing a complaint similar to those described above, information should be added in the “Special Considerations” section that advises of the corrective action as stated below.

If there is a service repair on record and it addresses a complaint similar to the ones noted in the first paragraph, information should be added in the “Special Considerations” section that advises of further corrective action (as listed below) if a future complaint is received.

SO Number	Number of Spacers to Remove at Front Axle TSB03-130-002 Kit #S-1597-001	Replace Pedestals TSB03-130-001A Kit #S-1588-001A
40520	3 of 3	
40521	3 of 3	
40522	3 of 3	
41118	3 of 3	
39824	4 of 5	
40546	3 of 5	
40793		X
40984		X
41208		X
41215	2 of 3	
41511		X
41519	2 of 3	
41608	2 of 3	
41609	2 of 3	
41610	2 of 3	
41710	3 of 3	
41752		X
41753	3 of 3	
42081		X
42150		X
42306		X
42495		X
42665	1 of 3	
42699	2 of 2	
42700	2 of 2	